



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining


MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

February 3, 2011

Reviewed: 

Mine Name: Fox Canyon	Permit Number: S/049/0080
Operator Name: Beck and Beck Construction Co.	Inspection Date: February 1, 2011
Inspector(s): Lynn Kunzler, Brett Gregory, Emily Berry	Time: 10:20 am
Other Participants: Darren Devy	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

To check status of site and take potential enforcement action.

Inspection Summary:


Prior to the inspection, it was noted that the operator has still not completed the permitting of this operation. A deficiency letter was sent October 2010 that has yet to be addressed. Among other items, it was noted that the operation has not paid the annual permit fee for the last 2 years, and that there is no reclamation surety. A letter was sent October 20, 2010 requesting the surety be submitted by November 4, 2010. While there has been some discussion with the operator and a surety company regarding this matter, nothing had been finalized.

Upon arrival at the site it was noted the operation was active. Material was being screened and loaded for a highway reconstruction project on Hwy 92. Because of the lack of surety, Cessation Order # MC-2011-17-01 was issued for not providing a reclamation surety prior to conducting mining operations. It was explained to the operator his appeal opportunities, including requesting a Stop Work conference.

Photos were taken to document site conditions.

Conclusions and Recommendations:

Operator needs to remit the past due permit fees of \$300, as well as post a reclamation surety in the amount of \$25,000.

Inspector's Signature 

cc: Dana Beck, Operator

O:\M049-Utah\S0490080-FoxCanyon\inspections\Insp-02012011.doc